



March 14, 2013

Badgerland Excavating, LLC  
Attn: Tim Van Bommel  
P.O. Box 258018  
Madison, WI 53725

RE: Town of Sumner, North Shore Road Post-Construction Inspection

Dear Tim,

A post-construction inspection was completed as scheduled yesterday afternoon. The inspection consisted of walking the Town of Sumner's portion of North Shore Road. I have enclosed a CD that contains the photographs of damaged areas of the road that need to be repaired. The damaged areas were marked in white paint.

There are approximately 13 potholes and 12 areas of cracking that need to be repaired. These areas were determined by comparing the area against pre and post construction photographs and video. The damaged areas were also examined for sharp edges and lack of soil deposits, both indicators of a newly formed crack or pothole. If you have any photographs or video of these areas being damaged prior to your project beginning, please forward them for our review.

Please contact the Town and let them know your schedule for getting these areas fixed. I would advise filling in the areas with cold mix immediately to avoid any further damage and thus making the repairs more costly in the summer months. Potholes should be saw cut square, filled with hot mix asphalt, and the joint hot pour crack sealed. Cracks shall be hot poured crack sealed. Edge failure or cracking may institute saw cutting, filled with hot mix asphalt, and hot poured crack sealed. If you have any questions or comments, please feel free to give me a call.

Sincerely,  
SNYDER & ASSOCIATES

Scott Anderson, P.E.  
Civil Engineer

Cc: Glendan Rewoldt, Town of Sumner with enclosures  
Rob Montgomery, Montgomery & Associates